UNCLASSIFIED

P 091302Z AUG 05 FM COMDT COGARD WASHINGTON DC//CG-45// TO AIG 4980 INFO COMCOGARD MLC LANT NORFOLK VA//V/VR// COMCOGARD MLC PAC ALAMEDA CA//V/VR// COGARD ENGLOGCEN BALTIMORE MD//011/014/024// COMDT COGARD WASHINGTON DC//G-OCS// UNCLAS /N09000//

COMDINOTE 9000

SUBJ: SAFETY RECALL NOTICE FOR SUZUKI OUTBOARD MOTORS

- SUZUKI MOTOR CORPORATION HAS ISSUED RECALLS ON THEIR SUZUKI DF200, DF225. AND DF250 OUTBOARD ENGINES IN JULY 2005.
- 2. THE JULY 2005 VOLUNTARY RECALL, AS OUTLINED IN SERVICE BULLETIN, EFFECTS SUZUKI DF200, DF225, AND DF250 OUTBOARD ENGINES WITHIN A CERTAIN SERIAL RANGE. EFFECTED ENGINES MAY HAVE A FLYWHEEL CAST WITH INCORRECT MATERIAL AND MAY EXPERIENCE FLYWHEEL BREAKAGE WITHOUT WARNING DURING ENGINE OPERATION. IF THE FLYWHEEL BREAKS, DEBRIS FROM THE BROKEN FLYWHEEL MAY BREAK THROUGH THE FLYWHEEL COVER AND ENGINE COVER, POSSIBLY CAUSING SEVERE PERSONAL INJURY.
 - A. THE ENGINE MODELS AND SERIAL NUMBERS POSSIBLY EFFECTED ARE LISTED BELOW.

MODEL	ENGINE SERIAL NUMBER RANGE	
DF200T	20001F-421546 THROUGH 421911	
DF200Z	20001Z-421114 THROUGH 421149	
DF225T	22501F-421292 THROUGH 421690	
DF225Z	22501Z-421084 THROUGH 421192	
DF250T	25001F-422026 THROUGH 422417	
DF250Z	25001Z-421296 THROUGH 421384	

- 3. ALL UNITS WITH SUZUKI DF200, DF225, AND DF250 OUTBOARD ENGINES ARE DIRECTED TO COMPLETE THE FOLLOWING ACTIONS UPON RECEIPT OF THIS MESSAGE:
 - A. IDENTIFY THE SERIAL NUMBER OF THE SUZUKI ENGINE.
- IF THE SERIAL NUMBER FALLS WITHIN THE POSSIBLY EFFECTED RANGE LISTED ABOVE, NOTIFY AN AUTHORIZED SUZUKI DEALER TO SCHEDULE A RECALL INSPECTION OF THE FLYWHEEL.
- C. FURTHER INFORMATION IS IN SERVICE BULLETIN NUMBER 08 DATED 07/21/05, LOCATED AT

HTTP://CGWEB.COMDT.USCG.MIL/G-SEN/G-SEN1/BOATS.HTM. THIS SERVICE BULLETIN SHALL BE MAINTAINED IN THE RESPECTIVE MAINTENANCE HISTORY FOLDER.

- 4. REQUEST WIDEST DISSEMINATION.
- 5. DIRECT QUESTIONS CONCERNING THIS SAFETY RECALL NOTICE TO CG-451 POC LTJG WILLIAM G. IOVEN AT 202-267-4171.
- INTERNET RELEASE AUTHORIZED.

BT

NNNN